



I'm not sure why we need the 100 ohm resistor. There is no noticable voltage drop feeding it with 5V peak to peak. We do need a louder speaker though.

Rob Frohne	
WWU	
Sheet: /	
File: Laser Tag.sch	
Title: Laser Tag	
Size: USLetter	Date: 2019-01-22
KiCad E.D.A. kicad 5.1.6+dfsg1-1	Rev: 0.2
	Id: 1/1